Bugfixes

2016-17.03

Technical Inquiries

Please ask the responsible contact person in our support department.
E-mail: e3-support@zuken.com

Note:

Zuken is not responsible for any errors, which may appear in this documentation. Liability, due to direct and indirect losses resulting from the delivery or use of this documentation, is excluded to the extent permitted by law. This documentation contains copyrighted information. All rights, especially those pertaining to the duplication and distribution as well as the translation, are reserved. This documentation, whether wholly or in part, may not be reproduced in any form (photocopy, microfilm, etc.), or processed, duplicated or distributed using an electronic system without Zuken's prior written consent.

Contact

Zuken E3 GmbH
Laemmerweg 55
D-89079 Ulm/Einsingen

Phone : +49 7305 9309-0
Fax: +49 7305 9309-99
Web: http://www.zuken.com
E-mail: e3-info@zuken.com

Bugfixes

The bug fixes are sorted and listed by designer number(s). This enables you, for example, to easily search for bugs reported to our support office.

Designer-20587	Trigger "AfterModifyNetSegment" doesn't react when symbol moved
Designer-22568	COM method 'Sym.GetAssignedOptionIds' returns 0 when Boolean expression is defined
Designer-26293	Wrong display of conductor logic lines when cutting/inserting a splice whose symbol contains the node property 'Passes wires'
Designer-26340	The model name can be larger than the allowed 52 characters via 'rename'
Designer-27727	No ability to set bus pins equivalently in DBE - This function is not possible and is canceled with error message now
Designer-28141	Borrowed licenses (BORROW Feature in FlexIm) permanently lead to 'Feature-Checkouts' when E3 is connected to a network
Designer-28279	Conductors/wires are missing after Ruplan import
Designer-28308	Panel: Autorouting: Wires are not straightly routed in specific combinations - Wire loop may occur at pin
Designer-28343	Symbols are missing/incorrect symbols ? are displayed at 'open line ends' after Ruplan Import
Designer-28482	Differing behavior when copying sheets with assemblies and terminal strips.
Designer-28492	Routing is not able to find the cable duct
Designer-28496	Formboard table symbol can't display text type #1096 (pin and port name)
Designer-28530	Docking points may appear on cable ducts
Designer-28584	Update in project of symbol in single pin display changes the signal display
Designer-28586	No ability to use a text template symbol when creating a model of type cable duct or mount
Designer-28669	Insert of a sub-circuit incorrectly inherits the location (function) of

	sheet when a template symbol of assembly designation is contained
Designer-28690	COM: No ability to reset values via SetTextStyle in the Dimension Interface
Designer-28694	Line ends belonging to different options are connected after delete or update of a symbol
Designer-28698	No ability to delete terminal in Multiuser (Your changes were not accepted by the server)
Designer-28708	Not all panel connections are routed in a variant
Designer-28717	Error 'E - Error in function string\next_string_from_chain(), ret = 1' when executing the COM function 'Tree.GetNames'
Designer-28726	When jumping to a text which is located outside the region, the red message 'E - Error in Function hnhlight\highlight_text(), ret = 2' appears
Designer-28776	COM: Function 'Opt.GetAllDeviceIds' returns also Attribute-Ids - with different attribute values
Designer-28780	Error 'E - Error in function hnbuspin\get_buspin_pins(), ret = 1' when saving a symbol within the database editor and updating a component at the same time
Designer-28797	No update of Formboard table symbol at import of a sub-circuit
Designer-28800	E3.ReportScripts: Incorrect creation of bill of material at devices with options in assemblies
Designer-28810	Symbols in a view (incl. Formboard) lose their assignment at sub-circuit import because of the update of the component depending on different component structures
Designer-28820	Error at change of cable ducts via device properties with tree structure using alternative component names.
Designer-28821	No function of change at zoom factor for ''Jump'' at already opened sheets
Designer-28827	COM function 'NetSeg.GetLineSegments' on net loops returns no coordinates
Designer-28830	Error ''Connection not unique'' when trying to connect a wire to a connection with variants
Designer-28851	When the start parameter "nopanel" is used, the menu entry "Autorouting" appears twice within the settings
Designer-28860	Cut and paste of locked models leads to error message E - Error in Function hnsheet\get_sheet_region(), ret = 2
Designer-28868	Open sheet "Read Only" from Sheet Overview opens sheet editable
Designer-28874	Setting 'Hyperlink - Text Hyperlink' for a hyperlink text are not regarded for the exports (except PDF) - colour/underline of the text
Designer-28879	Cable ducts placed in Panel are invisible in the 2D view
Designer-28897	COM call 'Dimension.Create' throws server exception "80010105"
Designer-28901	Update configuration in project is not updating the material information if the type of wire colors and hose/tube materials has been changed in database
Designer-28918	COM functions 'Sym.SetDisplayWidth' and 'Sym.SetDisplayLength' doesn't work for dynamic symbols which are placed on inactive sheets
Designer-28932	Segment merging formboard nodes are displayed as filled graphic in pdf (point instead of circle)
Designer-28933	When options have been added in the default mode, options with

	the same name (from different groups) are deleted when converting
Designer-28947	E3 crash when opening a specific project
Designer-28954	Import of sub-circuit is rejected in Multiuser (More than one symbol with the designation 'xxx' found)
Designer-28978	Rubber-Banding auxiliary line disappears when the cursor moves over the pin in connection direction
Designer-28998	Too many attributes are shown in device properties after conversion of the project
Designer-29028	Attribute settings in connection target reference format get lost when saving a file in "*.e3t or *.e3d" format

Americas

North America
Zuken USA Inc.
Westford, MA 01886, USA
Tel: +1 978 692 4900

Asia

Japan
Zuken (World Wide Head Office)
Yokohama, Kanagawa 224-8585, Japan
Tel: +81 45 942 1511

China
CIM-TEAM Software Technology Co., Ltd.
Changning District, Shanghai, China, 200336
Tel: +86-21-52280180

Korea
Zuken Korea Inc.
Seoul 135-283, Korea
Tel: +82 2 5648031

Singapore
Zuken Singapore Pte Ltd.
#22-05 Gateway East, Singapore 189721
Tel: +65 6392 5855

Taiwan
Zuken Taiwan Inc.
Taipei 110, Taiwan
Tel: +886 2 7718 1116

Europe

Germany
Zuken GmbH (European HQ)
D-85399 Hallbergmoos, Germany
Tel: +49 89 7104059 00

Zuken E3 GmbH
D-89079 Ulm, Germany
Tel: +49 7305 9309 0

Zuken E3 GmbH
D-30659 Hannover, Germany
Tel: +49 511 8595 9489

Switzerland
Zuken E3 GmbH
CH-5506 Mägenwil, Switzerland
Tel: +41 56 437 08 90

United Kingdom
Zuken UK Ltd.
Bristol, BS32 4RF, UK
Tel: +44 1454 207 801

France
Zuken S.A.
#91974 Les Ulis Cédex, France
Tel: +33 1 69 29 48 00

Italy
Zuken S.r.l.
20090 Milanofiori Assago, Milan, Italy
Tel: +39 02 575 921

Netherlands
Zuken GmbH
NL-6075 HA Herkenbosch, The Netherlands
Tel: +31 475 520 998

www.zuken.com/e3

ZUKEN™